



Instruction Manual Surface Mount Box


- 1 Carefully open the box by pressing the sides of the cover.




- 2 Use a utility knife to open the cable entry cutout.




- 3 Position the RJ45 keystone jack with its locking tab facing down.



- 4 Insert the RJ45 keystone jack at an angle, placing its locking tab between the two retaining clips of the surface mount box.



- 5 Secure the cable at the designated fixing point with a cable tie, without deforming the cable.



- 6 Close the surface mount box and check that the cover snaps into place. Label the network outlet.

