MPO/MTP® CONNECTOR AND ADAPTER CLEANING PEN

DESCRIPTION

The MPO/MTP® Connector and Adapter Cleaning Pen is designed for fast and effective cleaning of MPO/MTP® multi-fiber connectors and adapters used in data centers and other high-density fiber optic networks. Its simple push-to-clean mechanism gently removes dust and contaminants from exposed connector end faces and connectors installed in adapters, ensuring reliable optical performance and minimizing signal loss.



APPLICABLE STANDARDS

• Directive 2011/65/EU (RoHS); • Regulation (EC) No 1907/2006 (REACH)

MAIN FEATURES

Efficient Cleaning	Removes dust, oil, and other contaminants to maintain optimal signal quality.
360° Cleaning Action	Rotating cleaning tip ensures complete ferrule end-face coverage.
Click Confirmation	Audible click indicates successful cleaning operation.

PHYSICAL SPECIFICATIONS

Dimensions (mm)	250x50x15
Weight (kg)	0,050
Color	Grey
Number of Cleaning Cycles	≥600
Cleaning Method	Dry (non-abrasive, chemical free)
Compatible Connectors and Adapters	MPO with 8, 12, 24, 48 and 72 fiber connectors
End Face Compatibility	Flat and 8° angled (compatible with or without pins)
Key Orientation	Centered

LOGISTICS INFORMATION

	Unitary Box		Inner Box			Outer Box			EAN
Code	Weight (kg)	Dimensions (mm)	Weight (kg)	Dimensions (mm)	Quantity (un)	Weight (kg)	Dimensions (mm)	Quantity (un)	
81820103000	0,062	205x50x15	0,720	300x225x50	10	8,10	500x350x300	100	5608445047380


This document is authored and owned by barpa . It is forbidden to reproduce in whole or in part without mentioning its authorship, as well as modification of its content or context. All specifications are subject to change without notice.
The pictures/drawings are merely illustrative.
More information: info@barpa.eu or in www.barpa.eu

MPO/MTP® CONNECTOR AND ADAPTER CLEANING PEN


INSTRUCTIONS

For MPO/MTP® Adapters


1. Remove the guide cap from the device



2. Insert tip of cleaner into MPO/MTP® Adapter




3. Push the outer shell until it clicks




For MPO/MTP® Connectors


1. Open the cover on the guide cap



2. Insert the connector into the guide cap



3. Push the outer shell until it clicks



This document is authored and owned by barpa . It is forbidden to reproduce in whole or in part without mentioning its authorship, as well as modification of its content or context. All specifications are subject to change without notice.
The pictures/drawings are merely illustrative.
More information: info@barpa.eu or in www.barpa.eu

datasheet nº b247_0 | date: 10/26
approved by: Ana Barbosa